CVe Monitor® Access Start-Up Guide

To use the full capabilities of the **CVe Access Monitor (CVe AC)**, a ProFile® Access account is required. Contact Progressive's System Monitoring team to request your account activation and login credentials at:

SystemMonitoring@procomps.com **1-847-487-1000**




STARTING THE CVe AC MONITOR

CVe Monitors arrive in *Shelf Mode* to preserve battery life during storage and transportation.

To start the CVe-AC Monitor:

- **Press the front button** once to wake the monitor and enter normal operating mode.

ACCESSING YOUR PROFILE ACCESS ACCOUNT



After your account is created, you will receive a link to access the **ProFile Access** web page.


You can also access ProFile via the mobile app:

Download on the App Store

GET IT ON Google Play

iOS

Android




Download the ProFile app to view and export monitoring reports, manage preventive maintenance, and centralize tool documentation.

PROGRESSIVE COMPONENTS

ProFile®

PAIRING THE CVe AC WITH A MOBILE DEVICE

- **Open the ProFile app** on your device **and log in**.
- **Go to the Assets tab** and **select the tool** linked to your monitor. A unique serial number is on the bottom of the monitor.



NOTE:

- *All assets must be added to your account before pairing with the monitor.*
- *Ensure the monitor and mobile device are within range—max. 30–50 feet/10-15 meters.*

- **Tap the Bluetooth "Connect" button** in the app.
  - » Bluetooth connects automatically within a two-minute cycle, allowing for uninterrupted data collection during production.
- **Press and hold the front button on the monitor** for about 3 seconds to activate Bluetooth.
  - » You only need to pair once per mobile device.
- When prompted for a **pairing code**, enter:



iOS iPhone/iPad	Android Phone/Tablet
1987	001987

NEED ADDITIONAL SUPPORT?

For technical questions, additional support, or to learn more about Progressive's range of mold monitoring solutions, please contact a member of our System Monitoring team. Global contact information is available at: **ProFile-System.com/about/**

SystemMonitoring@procomps.com

1-847-487-1000 | 1-800-269-6653

www.ProFile-System.com

For additional information on Progressive Components, its extensive line of Mold Monitoring solutions, or its full line of component standards and exclusive innovations for the production tooling industry, please visit www.procomps.com.

©2026 Progressive Components International Corporation.

US Patents: 8,899,955, 8,883,054, & 10,715,464. European and Chinese patents applied for and issued.

PROGRESSIVE COMPONENTS

ProFile®